

Menu


HISTORY FILE MAP for year 2009

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



096.23:07-23:59 DSS-14 S-band MASER failure. HEMPT used instead but with much lower performance. All 1024bps data either lost or bad. Playback data for DOY 095 also affected. DR G109345 refers.